

Message Text

LIMITED OFFICIAL USE

PAGE 01 SUVA 00952 090437Z
ACTION OC-06

INFO OCT-01 EA-10 ISO-00 CCO-00 SY-05 /022 W

-----128586 100401Z /73

R 070130Z JUN 78
FM AMEMBASSY SUVA
TO SECSTATE WASHDC 7478
INFO AMEMBASSY CANBERRA
AMCONSUL HONG KONG
AMEMBASSY MANILA

LIMITED OFFICIAL USE SUVA 0952

WASHINGTON FOR OC AND NSU

CANBERRA FOR RSO AND TSO

HONG KONG FOR RTC

MANILA FOR RCO

E.O. 11652: N/A

TAGS: ASEC

SUBJECT: CRU CONSTRUCTION

REF: PHONE CALL 6/7/78

POST HAS SEVERAL QUESTIONS CONCERNING CONSTRUCTION IN CRU AREA:

A) PCV CONDUIT HAS BEEN USED FOR LIGHTS AND MAIN POWER.
PVC FOR LIGHTS EXTENDS THROUGHOUT VAULT AREA. MAIN
IMCOMING POWER IS STOPPED AT PENETRATION INTO VAULT. ALL PVC
IS BURIED IN APP. 4 INCHES OF CONCRETE. NO CHASEWAYS USED
IN BUILDING. CONSEQUENTLY CONDUIT PLACED IN DECKING THEN DECKING
IS POURED. THIS ALSO PERTAINS TO WINDOW WASH SYSTEM SHOWN IN
AREA. THIS SYSTEM HAS BEEN BROKEN AND CEMENTED IN. PLEASE ADVISE
LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 SUVA 00952 090437Z

IF THIS SETUP IS ACCEPTABLE AND , IF NOT, WHAT STEPS CAN BE TAKEN
TO BRING IT UP TO STANDARD.

B) SINCE NO T-BARS AVAILABLE LOCALLY PROPOSE TO USE
4 1/2 INCH BOLTS PER SHEET OF STEEL, TWO AT TOP, TWO AT
BOTTOM. CONTINUOUS WELD AT SEAM.

C) TOILET FACILITIES ARE SHOWN ON PRINTS. BECAUSE NO PLUMING HAS BEEN BROUGHT INTO AREA AT THIS TIME AND DUE TO ITEM FACTOR, AND SLOWNESS OF WORKERS, PROPOSE TOILET FACILITIES BE DROPPED FROM PRINTS. FACILITIES ARE AVAILABLE TWENTY FEET FROM VAULT DOOR ACROSS STAIRWELL.

D) REQUEST STATUS AND ETA FOR GENERATORS AND AC UNIT FOR CRU AREA.

CONDON

NOTE BY OC/T: TELEGRAM DELAYED IN TRANSMISSION.

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptoning: X

Capture Date: 01 jan 1994

Channel Indicators: n/a

Current Classification: UNCLASSIFIED

Concepts: n/a

Control Number: n/a

Copy: SINGLE

Draft Date: 07 jun 1978

Decaption Date: 01 jan 1960

Decaption Note:

Disposition Action: RELEASED

Disposition Approved on Date:

Disposition Case Number: n/a

Disposition Comment: 25 YEAR REVIEW

Disposition Date: 20 Mar 2014

Disposition Event:

Disposition History: n/a

Disposition Reason:

Disposition Remarks:

Document Number: 1978SUVA00952

Document Source: CORE

Document Unique ID: 00

Drafter: n/a

Enclosure: n/a

Executive Order: N/A

Errors: N/A

Expiration:

Film Number: D780242-0867

Format: TEL

From: SUVA

Handling Restrictions: n/a

Image Path:

ISecure: 1

Legacy Key: link1978/newtext/t19780684/aaaacuks.tel

Line Count: 73

Litigation Code IDs:

Litigation Codes:

Litigation History:

Locator: TEXT ON-LINE, ON MICROFILM

Message ID: 1dcdcc8f-c288-dd11-92da-001cc4696bcc

Office: ACTION OC

Original Classification: LIMITED OFFICIAL USE

Original Handling Restrictions: n/a

Original Previous Classification: n/a

Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: n/a

Previous Classification: LIMITED OFFICIAL USE

Previous Handling Restrictions: n/a

Reference: n/a

Retention: 0

Review Action: RELEASED, APPROVED

Review Content Flags:

Review Date: 02 may 2005

Review Event:

Review Exemptions: n/a

Review Media Identifier:

Review Release Date: n/a

Review Release Event: n/a

Review Transfer Date:

Review Withdrawn Fields: n/a

SAS ID: 2447348

Secure: OPEN

Status: NATIVE

Subject: CRU CONSTRUCTION

TAGS: ASEC

To: STATE

Type: TE

vdkvgwkey: odbc://SAS/SAS.dbo.SAS_Docs/1dcdcc8f-c288-dd11-92da-001cc4696bcc

Review Markings:

Sheryl P. Walter

Declassified/Released

US Department of State

EO Systematic Review

20 Mar 2014

Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014